Issued by	Introduction from serial No.	Date	Product affected	P/B No
J.Ralph		5-9-13		006 300 030_GB/09.2013/Redditch

Title / Subject		Reg No.	Edition / Ref. No.	Page
EB+ Gen3 AM Kit				1 of 1

EB+ Gen2 & Gen3 replacement

Service Kit   950 823 008 & 950 823 034

Software
DIAG+ Version 6.10 or later ✔

Go to **www.haldex.com** and enter the Findex section to down load the latest software

Software
DIAG+ Version 5.12, 5.16, 5.18 ✘

950 800 909 EB+ Interface Kit
Contents: 815023001 USB PC interface
042707309 USB cable ✔

815 001 401 ✘

Down load software here

814 036 001 (6.5m)	814 001 601 (6.5m)
814 036 011 (15m) ✔	814 001 611 (15m) ✘
814 036 021 (20m)	814 001 621 (20m)

EB+ Info Centre 2

EB+ Info Centre 1

ISO12098 / ISO1185 (24N)

ISO7638

364 604 001

814 037 001 (6.5m)
814 037 011 (0.5m)
814 037 021 (8.0m)
814 037 031 (14m)

814 019 001 (6.5m)
814 019 011 (0.5m)
814 019 021 (8.0m)
814 019 031 (14m)

DIAGN

Haldex Brake Products, Redditch, UK
www.haldex.com