


### New Service Housing Assembly for all Drum Brake 3030L Spring Brakes



Starting in January 2011 all 76mm stroke Anchorlok® spring brakes will have a new stronger service housing. Part numbers that are affected by this change are shown in the table. The new service housing is thicker and has a distinctive stamped profile to increase rigidity. The new housing provides over 40% greater durability than the original product.

| Blue Seal® Part Number | Description | Stroke (mm) | Pushrod Length (mm) |
|------------------------|-------------|-------------|---------------------|
| 1363030001             | 3030L       | 76          | 246                 |



Original, flat bottom housing 3.43mm (.135 in) thickness

New thicker shaped housing 3.88mm (.149 in) thickness

Please review your application with the product change to ensure all performance and safety requirements are met.

If you have questions or require additional documentation concerning this change, please contact your local Haldex Sales Professional.

L55335W US Rev 3/11 WEB ONLY

#### Haldex Commercial Vehicle Systems

Haldex Europe  
 30 Rue du Ried  
 Weyersheim - FR - 67728 Hoerdt Cadex  
 Phone: +33 3 88 68 22 00  
 Fax: +33 3 88 68 22 09

[www.haldex.com](http://www.haldex.com)