

Service Kit 950 364 824
950 364 825
950 364 826


950364824 = 364569001
950364825 = 364570001
950364826 = 364571001

051 5132 09



1


ISO 7638
ISO 12098 / ISO 1185 (24N)



2




3




4



5




6



7



8



9

ABS System U-ABS ECU

ECU replacement
ECU ersatz
Remplacement de l'UCE



www.haldex.com

10




Torque = 3.4 / 4.0 Nm


11



12




13



ISO 7638
ISO 12098 / ISO 1185 (24N)

14



15



16



"Click" + "Click" =



www.haldex.com