



This Haldex Air Dryer is equipped with an Integrated Turbo Protection Valve which replaces the External Turbo Protection Valve at the air dryer inlet. Installation of this air dryer may require adding a 45° or 90° fitting at the inlet in order to complete the plumbing.

Old Air Dryer



New Air Dryer



For additional information contact the Haldex Technical Services Department: 1-800-643-2374

7/03 1.5M ART L31188 (Created 12/02)