

Issued by
Günter Leiberich

Introduction from serial No.

Date
04.2020

Product affected
ABS

P/B No
H 099

Title / Subject

Reg No.

Edition / Ref. No.

Page

3.

2

Phase-out ABS parts and ABS cables.

Due to low demand, we intend to discontinue the listed components with immediate effect.

There will be no direct replacement. The current stock can be sold off.

ITEM NUMBER	CATEGORY	ITEM NUMBER	CATEGORY
074151	ABS/EBS accessories	364137101	ISO 7638 power cable
364077001	sensor extension cable	364137111	ISO 7638 power cable
364096101	ISO 7638 power cable	364137121	ISO 7638 power cable
364096102	ISO 7638 power cable	364137161	ISO 7638 power cable
364096112	ISO 7638 power cable	364142001	Modal
364096122	ISO 7638 power cable	364173011	MRV cable
364096151	ISO 7638 power cable	364173021	MRV cable
364097021	ISO 3731 (24S) power cable	364194001	ISO 1185 (24N) power cable
364114021	ABS	364212001	sensor extension cable
364115121	Modal	364212011	sensor extension cable
364119001	sensor extension cable	364212021	sensor extension cable
364119021	sensor extension cable	364212031	sensor extension cable
364119031	sensor extension cable	364212041	sensor extension cable
364119041	sensor extension cable	364258001	ABS MODAL
364119051	sensor extension cable	364258011	ABS MODAL
364120021	sensor extension cable	364258031	ABS MODAL
364120051	sensor extension cable	364263001	ABS MODULAR 2
364121021	sensor extension cable	364277011	ABS MODAL
364121031	sensor extension cable	364307001	ECU connection loom
364121041	sensor extension cable	364307011	ECU connection loom
364122071	MRV cable	364307021	ECU connection loom
364122081	MRV cable	364307031	ECU connection loom
364122091	MRV cable	364329001	ECU connection loom
364122101	MRV cable	364329011	ECU connection loom
364122111	MRV cable	364329021	ECU connection loom
364122121	MRV cable	364338001	ECU connection loom
364122131	MRV cable	364338011	ECU connection loom
364122141	MRV cable	364338021	ECU connection loom
364122151	MRV cable	364341011	ECU connection loom
364124001	ISO 1185 (24N) power cable	364346001	ECU connection loom
364136001	sensor extension cable		

PRODUCT BULLETIN



Issued by
Günter Leiberich

Introduction from serial No.

Date
04.2020

Product affected
ABS

P/B No
H 099

Title / Subject

Reg No.

Edition / Ref. No.

Page

3..

2

ITEM NUMBER	CATEGORY
364347011	ECU connection loom
364348001	ECU connection loom
364357011	ISO 7638 power cable
364358011	ISO 1185 (24N) power cable
364358031	ISO 1185 (24N) power cable
364364001	ISO 7638 power cable
364368071	ISO 7638 power cable
364370001	ISO 1185 (24N) power cable
364375001	ISO 7638 power cable
364375021	ISO 7638 power cable
364377011	diagnostic cable
364381001	ABS MODULAR 2
364433001	ECU connection loom
364439001	ECU connection loom
364454001	EPV valve cable
364594011	ISO 7638 power cable
393585001	ABS exciter
393585011	ABS exciter
950364016	ABS repair
950364050	MRV cable
950364054	sensor extension cable
950364504	Wheel sensor unit
950800904	EBS Repair
003846709	POA Info center