


Installation Guide

L31143 (Last Rev. 9/03)

ABS Power Cable Repair Kit

Haldex Part Number AQ15473



NOTE: Occasionally wire color is substituted due to availability. BEFORE inserting terminals into connector insure individual wire's functionality.

TO REPAIR CABLE:

1. Strip 1/4 inch of insulation from wire.
2. Fit seal (102717-A) over insulation.
3. Fit and crimp terminal (101712-EL or 101712-CY) on wire and seal.
4. Insert terminals in correct locations of connector.

L31143 US 1/07 5M ART (Last Rev. 9/03)

www.haldex.com - www.hbsna.com



Commercial Vehicle Systems


Haldex Brake Products Corporation
10707 N.W. Airworld Drive,
Kansas City, MO 64153
Phone: (816) 891-2470
Fax: (816) 801-4198

Haldex Limited
525 Southgate Drive, Unit 1
Guelph, Ontario CAN N1G 3W6
Phone: (519) 826-7723
Fax: (519) 826-9497

Installation Guide

L31143 (Last Rev. 9/03)

Juego Reparación del Cable de Poder ABS Número de Parte Haldex AQ15473



PARA REPARAR EL CABLE:

1. Remueva $\frac{1}{4}$ de pulgada de aislante del cable.
2. Adapte el sello (102717-A) sobre el alambre de aislamiento.
3. Adapte y ajuste la terminal (101712-EL ó 101712-CY) en el cable y sello.
4. Inserte las terminales en los lugares correctos en la pieza de conexión.

