

Worn Off Either Side of Shoe Table




Rusted Holes in Shoe Table




Torch Damage



Broken Welds



Flared and Damaged Cam Ends



Ears on Web Bent



Bent Shoe Table Ends



Elongated Rivet Holes



Deteriorated Table



**Common Core Defects
No Credit Given**